












TKK 90	880-890	2000	695
TKK 100	980-990	2000	695








- 6 kom 4 x 10
- 8 kom 4 x 40




-a-





-b-




-2-




-c-




-d-




⋮





6 X




6 kom 4 x 40





Ø6 mm




8 kom 4 x 40



-e-




Ø6 mm



880 mm...TKK90

980 mm...TKK100




1 mm


-3-

-4-


-f-




-h-




-i-




3 X 4 X 10
 6 X
 Ø 3.2 mm



3.2 mm
 min
 15







2




1

-g-



1
 2
 L
 R



A







-5-

-5-





-6-

L:D


-j-







-k-



-l-




10 Nm




-7-

-8-



Shema pozicij Assembly Drawing

TKK ATLAS



1		x2	2		x1	3		x1	4		x2	5		x2
6		x2	7		x2	8		x2	9		x2	10		x2
11		x2	12		x2	13		x1	14		x1	15		x1
16		x8	17		4x30 x8	18		4x10 x6	19		x6			